

New Jersey Police Crash Investigation Report

Reportable
 Non-Reportable
 Change Report

02	1 Case Number 11-44658	10 Crash Occurred On Rt 40	11 Speed Limit 50	12 Route No. Suffix 40	13 Milepost 045	18 Speed Limit 03	118a 02
01	2 Police Dept of Twp of Hamilton	Code 01	At intersection with Road Name CR 552		17 Cross Road Name CR 552		118b --
02	3 Station/Preinct	4 Date of Crash mm dd yy 12 16 11	5 Day of Week Su M Tu W Th Sa Th	6 Time (use 240 hrs) 01480112	7 Municipality Code -	8 Total Killed 0	9 Total Injured 01
04	23 Vehicle No	24 Policy No	25 Ins Code 426	26 Ins Code	27 Ins Code	28 Ins Code	119a --
02	01	<input type="checkbox"/> Parked <input type="checkbox"/> Prod <input type="checkbox"/> Pedalcyclist <input type="checkbox"/> Resp to Emergency <input type="checkbox"/> H&S Run	<input type="checkbox"/> Packed <input type="checkbox"/> Prod <input type="checkbox"/> Pedalcyclist <input type="checkbox"/> Resp to Emergency <input type="checkbox"/> H&S Run	29 Sex M	30 Driver's First Name Jason	31 Last Name Dare	32 Sex M
01	25 Driver's First Name Jason	26 Initial D	27 Last Name Dare	28 Sex M	33 Eyes 06	34 Number and Street	35 City
01	31 State NJ	32 Drivers License No	33 DOB mm dd yy 05 09 76	34 Expires mm yy 05 13	35 State	36 Drivers License No	37 DOB mm dd yy
11	35 Owner's First Name Jason	36 Initial D	37 Last Name Dare	38 Sex M	39 Number and Street	40 City	41 State
05	43 VIN 1D7RV1CT3BS583343	44 Year 11	45 Color Gray	46 State NJ	47 Make Dodge	48 Model Rum	49 Year 11
05	46 Vehicle Removed To American Auto	47 Authority Towed	48 Vehicle Removed To Driven <input type="checkbox"/> Left at Scene <input type="checkbox"/> Towed <input checked="" type="checkbox"/>	49 Authority Owner <input type="checkbox"/> Driver <input type="checkbox"/> Police <input checked="" type="checkbox"/>	50 VIN	51 Year	52 Color
01	48 Alcohol/Drug Test Given <input type="checkbox"/> No <input type="checkbox"/> Yes <input checked="" type="checkbox"/> Refused	49 Type Breath <input type="checkbox"/> Blood <input type="checkbox"/> Urine <input type="checkbox"/>	50 Results 0 % <input type="checkbox"/> Pending <input type="checkbox"/>	51 134 Crash Diagram (NOT TO SCALE)	52 Carrier No	53 USDOT <input type="checkbox"/> Other <input type="checkbox"/>	54 Carrier Name
01	54 Alcohol/Drug Test Given <input type="checkbox"/> No <input type="checkbox"/> Yes <input checked="" type="checkbox"/> Refused	55 Type Breath <input type="checkbox"/> Blood <input type="checkbox"/> Urine <input type="checkbox"/>	56 Results 0 % <input type="checkbox"/> Pending <input type="checkbox"/>	57 134 Crash Diagram (NOT TO SCALE)	58 Carrier No	59 USDOT <input type="checkbox"/> Other <input type="checkbox"/>	60 Carrier Name

See Attache

135 Accident Description
 Driver stated that he swerved to avoid a deer that ran into his path. He lost control and drove into the woods.
 Investigation: Vehicle was Westbound on Rt 40 at the CR 552 merge/intersection. Vehicle swerved to the left, jumping the low concrete median. Vehicle damaged its passenger side tires and continued onto the Eastbound berm where it became stuck in the mud. Vehicle had sustained prior damage from an earlier impact on the passenger side front fender/door area prior to this incident. It appears the vehicle struck a sign post or something similar on the westbound shoulder/berm area. Nothing was observed as damaged in the immediate area.

136 Damage To Other Property
Pending

137 Charge
39-4-50, 39-4-50.2, 39-4-97

138 Summons No
205277-79

139 Charge
Multiple Charges

140 Summons No

141 Officer's Signature
Ofc. J. Esposito

142 Badge No
18

143 Reviewed by

144 Case Status
Pending Complete

A	01	01	01	04	35	M	01	02	02	09	04	--	Driver #1
B													COPY
C													
D													
E													


New Jersey Police Crash Investigation Report

Motor Vehicle Crash Diagram

Police Dept: Top of Hamilton Code: _____

Station: May's Landing Case No: 11-44668

134 Crash Diagram (NOT TO SCALE)



COPY

[Signature]
Officer's Signature

18
Badge Number